

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave.St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-001458**Date Inspected:** 02-Feb-2008**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1600**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name:	N/A	CWI Present:	Yes	No			
Inspected CWI report:	Yes	No	N/A	Rod Oven in Use:	Yes	No	N/A
Electrode to specification:	Yes	No	N/A	Weld Procedures Followed:	Yes	No	N/A
Qualified Welders:	Yes	No	N/A	Verified Joint Fit-up:	Yes	No	N/A
Approved Drawings:	Yes	No	N/A	Approved WPS:	Yes	No	N/A
				Delayed / Cancelled:	Yes	No	N/A
Bridge No:	34-0006	Component:	OBG & 114 Meter Mock-Up				

Summary of Items Observed:

This Quality Assurance (QA) Inspector observed various fabrication and welding practices at Zhenhua Port Machinery Company (ZPMC) on Changxing Island in Shanghai, China today for the Self Anchored Suspension Bridge for San Francisco, California.

Orthotropic Box Girder (OBG)

This QA Inspector observed in Bay 1 the drilling of flange bolt holes on the flat closed u-rib plates and milling & machine beveling of flat closed u-rib plates for the partial joint penetration (PJP) and the machining of the 2 millimeter radius on hand access holes.

114 Meter Mock-Up

This QA Inspector observed the reaming of bolt holes in Bay 2 on the skin plates of this mock-up for joining the upper and lower sections together.

Summary of Conversations:

No conversations held today.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Mazen Wahbeh, (818) 292-0659, who represents the Office of Structural Materials

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

for your project.

Inspected By: Berger, Bruce

Quality Assurance Inspector

Reviewed By: Cochran, Jim

QA Reviewer